

**ACTON •  
MICKELSON •  
ENVIRONMENTAL, INC.**

**LOG OF BORING**

Facility: G-P Fort Bragg

Address: 90 W. Redwood Ave.  
Fort Bragg, CA

**MW-2.6**

5175 Hillsdale Circle #100  
El Dorado Hills, CA 95762

AME Project No.: 16017.08

Area No./ Description: Parcel 2, Breezeway

Page 1 of 1

Drilling Company: RSI  
Drilled By: Don Jenkins  
Drilling Method: Hollow Stem  
Boring Diameter: 8"  
Sampling Method: California Modified Split Spoon Sampler  
and Standard Penetration Test (SPT)

Location (East/North):  
Ground Surface Elevation:  
Water Depth (Date, Time): 5' (11/17/05 1310)  
Casing Elevation:  
Total Depth (feet): 14.5' BGS  
Weather: clear/warm

Drilling Started: 11/17/05 1130  
Drilling Finished: 11/17/05 1330

Logged By: J.D. Matthey, R.G., C.E.G  
Checked By:

Source: Original field notes

PID/FID: PID

DEPTH (feet)	SAMPLE		BLOW COUNTS		SOIL DESCRIPTION  SOIL NAME, COLOR, RELATIVE DENSITY OR CONSISTENCY, MOISTURE, PARTICLE SIZE RANGE, OTHER	GRAPHIC LOG	SOIL CLASS	WELL GRAPHIC	COMMENTS	FIELD PID READING (ppm)
	INTERVAL	SAMPLE ID	BLOWS/6 IN. (N)	IN. RECD/D					DRILLING RATE AND CONDITIONS, WATER DEPTH, BACKFILL	
0		MW-2.6-1.5	12-8-8 (16)	13	ASPHALT. FILL - SILTY GRAVEL (GM), black (2.5Y N2/), Medium Dense, Moist, 70% fine gravel, 0.5 cm clast, 20% fine sand, 10% fines.		GM		1140	0
5			4-10-16 (26)	0	FILL - SILTY SAND (SM), very dark gray (2.5Y N3/), Medium Dense, Moist, 70% fine sand, 30% fines.  grayish brown (2.5Y 5/2), Medium Dense, Wet, Fill? 80% fine to medium sand, 20% fines.		SM			
10			2-6-6 (12)		1" Rust Colored Layer.					
					light yellowish brown (2.5Y 6/3). SANDSTONE (SS), pale olive (5Y 6/4), KJfs, Moderately Hard.		SS		Boring Terminated Total Depth = 14.5'	